

**GENERAL PENALTIES – ALL CLASSES**

Updated: 2024-08-07

Car number	Score pool	Penalty points	Reason	Date
281	EDE	5	Status of Design Documents on 12.07: EDR submitted with wrong page size (too big drawings).	2024-07-30
269	EDE	5	Status of Design Documents on 12.07: DSS submitted with wrong car number in the header.	2024-07-30
260	EDE	20	Status of Design Documents on 12.07: No valid DSS submitted.	2024-07-30
239	Overall	30	Failing EV5.7.1, precharging to 85%, no safety concern, as this was the rule earlier, peak current is 1A.	2024-07-30
222	Overall	30	Violation of rule EV4.10.4, measurements outside respective containers.	2024-07-30
222	Overall	20	Violation of rule EV9.1.1, submitted ESF is clearly not identical to realised electrical system, the scrutineers were not informed and the teams solution is not rule compliant.	2024-07-30
243	BP	15	Penalty based on S1.4.2.	2024-07-31
269	BP	15	Penalty based on S1.4.2.	2024-07-31
169	Overall	20	Violation against CV 2.6.1. Fuel filler neck has smaller internal diameter than 35 mm.	2024-08-01
121	Overall	50	Violation against T 4.3.1 : less than 50 mm clearance between the envelope and Percy's head.	2024-08-01
288	Overall	75	Violation against T 4.5.3 . Team can not prove that the lap belt welds can withstand against 13 kN + bad engineering practice + poor execution.	2024-08-01
276	Overall	20	Internal cross section template does not fit everywhere	2024-08-01
281	Overall	20	Violation against T 3.3.3 no alloyed steel weld tests.	2024-08-01
113	Overall	25	Protest rejected.	2024-08-06
414	Overall	25	Protest rejected.	2024-08-06
613	Overall (DV)	25	Protest rejected.	2024-08-06
459	Overall	25	Protest rejected.	2024-08-07