

Post scrutineering penalties – Acceleration DV

Updated: 2024-08-03 18:00

Car number	Run	Penalty	Reason
613	2	0.3	ASSI did not turn off after ASMS off and EBS deactivation. Violation of T 14.9, Violation without advantage to the team IN 12.1.4
672	1	DQ	Datalogger violation
459	1	DQ	Run ended in AS Emergency
459	2	DQ	Run ended in AS Emergency
672	2	1	Wing clearance issue, IN 12.1.4 Group B