

Post scrutineering penalties – Acceleration Manual

Car number	Run	Penalty	Reason
621	2	DQ	Power limiter violation
663	1	DQ	Data logger was not connected (D9.4.4)
663	2	DQ	Data logger was not connected (D9.4.4)
299	2	1	Ground Clearance violated by tape over screw on underfloor, Group B penalty (IN 12.1.4)
281	1	1	Ground clearance, Group B Violation IN 12.1.4
281	2	1	Ground clearance, Group B Violation IN 12.1.4
109	2	1	Wing clearance, Group B Violation IN 12.1.4
224	1	DQ	Brake fluid leakage, IN 12.1.5
224	2	DQ	Brake fluid leakage, IN 12.1.5
146	1	DQ	Brake fluid leakage, IN 12.1.5
146	2	DQ	Brake fluid leakage, IN 12.1.5
177	1	1	Ground clearance, Group B Violation IN 12.1.4
138	1	DQ	Brake fluid leakage, IN 12.1.5
138	2	DQ	Brake fluid leakage, IN 12.1.5