

Post scrutineering penalties – Autocross Manual

Updated: 2024-08-03 19:00

Car number	Run	Penalty	Reason
678	1	DQ	Defect in bearing of right rear wishbone, Safety related issue IN 12.1.5
224	1	2	Ground clearance violation without advantage to the team, IN 12.1.4
261	1	2	Grease leakage, violation of T 7.2.4, violation without advantage to the team IN 12.1.4, not safety critical
261	2	2	Grease leakage, violation of T 7.2.4, violation without advantage to the team IN 12.1.4, not safety critical
222	1	5	Wing clearance issue, Group B violation IN 12.1.4
222	2	5	Wing clearance issue, Group B violation IN 12.1.4
261	3	DQ	Brake fluid leakage, IN 12.1.5
261	4	DQ	Brake fluid leakage, IN 12.1.5
299	1	DQ	Grease leakage, violation of T 7.2.4, violation without advantage to the team IN 12.1.4, not safety critical
613	3	2	Water leakage, violation of T 7.2.4, violation without advantage to the team IN 12.1.4, not safety critical
613	4	2	Water leakage, violation of T 7.2.4, violation without advantage to the team IN 12.1.4, not safety critical
222	3	DQ	Brake fluid leakage, IN 12.1.5
138	1	DQ	Brake fluid leakage, IN 12.1.5
195	3	2	Grease leakage, violation of T 7.2.4, violation without advantage to the team IN 12.1.4, not safety critical
195	4	2	Grease leakage, violation of T 7.2.4, violation without advantage to the team IN 12.1.4, not safety critical
121	1	5	Wing clearance issue, Group B 12.1.4
138	2	DQ	Engine oil leakage, Brake fluid leakage, IN 12.1.5
138	3	DQ	Engine oil leakage, Brake fluid leakage, IN 12.1.5
121	2	DQ	Defect in right rear wishbone, Safety Related IN 12.1.5
121	3	DQ	Defect in right rear wishbone, Safety Related IN 12.1.5