

## Post scrutineering penalties – Endurance

Updated: 2024-08-07 19:00

Car number	Penalty	Reason
660	30	Grease leakage, violation of T 7.2.4, violation without
		advantage to the team IN 12.1.4, not safety critical
109	DQ	Large oil leakage, environmental issue IN 12.1.5
113	30	Grease leakage, violation of T 7.2.4, violation without
		advantage to the team IN 12.1.4, not safety critical
261	30	TSAL visibility issue, violation of EV 4.10.8, violation without
		advantage
195	DQ	BOTS did not trigger, safety related issue, IN 12.1.5
281	30	Grease leakage, violation of T 7.2.4, violation without
		advantage to the team IN 12.1.4, not safety critical
207	DQ	BOTS did not trigger, safety related issue, IN 12.1.5
294	DQ	Oil leakage, safety critical issue IN 12.1.5
672	150	Grease leakage, violation of T 7.2.4, violation without
		advantage to the team IN 12.1.4, not safety critical
		Wing clearance issue, Group B IN 12.1.4
224	DQ	BOTS did not trigger, safety related issue IN 12.1.5